



TS - Sensor with Display SCD-1

outputs: RS 232, analog and alarm




FS - Sensor with Display SCD-1

outputs: RS 232, analog and alarm



MZ1 / MZH / MZB1 - Sensor with Display SCD-1

outputs: RS-232, analog and alarm



MZ - Sensor with Display SCD-1

outputs: RS 232, analog and alarm

