


# TS1-A10 - Sensor without integrated amplifier with Strain gauge amplifier SCV-1-A2

outputs: analog 0 - 10 V



# MZ-A10 Sensor without integrated amplifier with Strain gauge amplifier SCV-1-A2

outputs: analog 0 - 10 V

