

TS1-A10 - Sensor without integrated amplifier with Strain gauge amplifier SCV-1

outputs: analog 0 - 1 V

